Oil Field Environmental Incident Summary

Responsible Party: MARATHON OIL COMPANY **Well Operator:** MARATHON OIL COMPANY

Well Name: VMR TRUST 11-16TFH

Field Name: BAILEY Well File #: 24091

Date Incident:3/14/2015Time Incident:12:15Facility ID Number:County:DUNNTwp:146Rng:93Sec:9Qtr:

Location Description:

Submitted By: Chris Gitch Received By:

Contact Person: Chris Gitch

3172 HWY 22 N

DICKINSON, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 7 Barrels 7 Barrels 7 barrels

Other

Description of Other Released Contaminant:

Produced water

Inspected: Written Report Received: 4/2/2015 Clean Up Concluded: 3/14/2015

Risk Evaluation:

No immediate risk. Spill has been cleaned up.

Areal Extent:

Contained on well site

Potential Environmental Impacts:

No environmental impacts. Spill has been cleaned up.

Action Taken or Planned:

Corrective actions will be implemented by contractor.

Wastes Disposal Location: Waste will be disposed of at approved facility by contractor.

Agencies Involved:

Updates

Date: 3/16/2015 Status: Reviewed - Assigned to Other Agency Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to tank leak, remained on location within the diking according to the report. NDIC retains oversight.